

SAFETY

envoy

SAFETY
starts with
ME

@Envoy

Safety Alert

2017 - 01

ERJ-175 Waste Container

There has been an increased number in interior aircraft damages to the ERJ-175. These have been caused by the improper opening of the galley waste container door. The door is designed to be opened by pushing below the metal flip door and the door will release open.

Do not open the door by grabbing the edge of the panel and opening the door; this causes the panel to break over time. This is a non-differable item and will cause the aircraft to be placed out of service.

Incorrect Method of Opening



Correct Method of Opening



envoy

This information is intended solely for Envoy Air Inc. employees and may contain confidential and/or privileged information. Any review, dissemination, copying, printing or other use of this document by persons other than Envoy Air Inc. employees is prohibited.
Envoy Safety Hotline 800-477-3002