

DFW SAFETY ALERT 12/24/2016 CRJ-700/900 Lektro Strut Strap



CRJ-700/900 – Lektro Strut Strap must be placed around the shiny OLEO section of the nose gear strut. When the NLG is compressed to the extent the strap cannot seat evenly around the shiny OLEO with free up and down movement of the strut, notify the flight crew and maintenance as soon as is practicable to avoid a delay.

CAUTION

Do not place the winch strap around the barrel housing of the oleo on CRJ-700/900 aircraft or the nose landing gear may be damaged.

If you have any questions, please contact your Supervisor/Manager or the Safety Department.

Please work safely and efficiently.

You are the KEY to
SAFETY!



SAFETY MATTERS @ DFW