

**SAFETY**

envoy

**SAFETY**  
starts with  
**ME**

@Envoy

## Safety Alert 2017 – 02 ERJ-175 Load Limits

**E-175 cargo load line procedures must always be followed.**

A minimum of two (2) inches of clearance is required between the baggage and the ceiling of the cargo compartment.

Baggage **CANNOT** be loaded beyond the maximum loading height marked inside the cargo compartment.

### Forward Cargo Compartment:

- Load the majority of the cargo without exceeding the weight capacity of the bin
- **DO NOT LOAD** baggage above the cargo load line that indicates a minimum of 2 inches of clearance from the ceiling required for the fire suppression system.

Do not load above  
the bottom of this line



### Rear Cargo Compartment:

- Load all remaining baggage into rear compartment to avoid exceeding the cargo load line in the forward compartment
- **DO NOT LOAD** baggage above the cargo load line that indicates a minimum of 2 inches of clearance from the ceiling required for the fire suppression system.

**If baggage is loaded above the cargo load line it is a FAA violation of CFR 91.9 which can result in civil penalty. This also inhibits the fire suppression system to properly function in case of a fire in the cargo bin.**



This information is intended solely for Envoy Air Inc. employees and may contain confidential and/or privileged information. Any review, dissemination, copying, printing or other use of this document by persons other than Envoy Air Inc. employees is prohibited.

#### SMS Safety Tip

**Hazard: Any condition which could cause harm**  
Hazards May be Reported Using the Envoy Safety Hotline: 1-800-477-3002

envoy