

**DFW SAFETY ALERT 12/28/2016
EMB-175 N034 – Aircraft struck by Charlatte**



Aircraft N034 was damaged when a Charlatte came in contact with the fuselage causing a golf ball size dent to the right side of the cargo door.

- Please ensure you conduct a safety check on every equipment prior use.
- Contact GSE if any discrepancies are noted.
- Drive carefully. **DO NOT** exceed airport ramp speed limit.
- The maximum speed for all motor vehicles and ground equipment within the Diamond of Safety or **25 feet** from the nearest portion of the aircraft shall not exceed **3 - 5 miles** per hour (walking speed).
- **NEVER** drive into the “**DIAMOND OF SAFETY**” without stopping first.
- **NEVER** violate the 5-foot rule.

If you have any questions, please contact your Supervisor/Manager or the Safety Department.

Please work safely and efficiently.

You are the **KEY** to
SAFETY!



SAFETY MATTERS @ DFW